
From: Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]
Sent: 1/26/2015 12:42:07 PM
To: Ed Baine (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Edwar62]
Subject: FW: Ash Pond ABC inspection 01/26/15
Attachments: 20150126120909107.pdf

From: Jeffrey R Marcell (Generation - 3)
Sent: Monday, January 26, 2015 12:21 PM
To: Michael J Winters (Generation - 34)
Cc: John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3); Kenneth Roller (Services - 6)
Subject: RE: Ash Pond ABC inspection 01/26/15

Attached.

No discharge at C Pond. Some standing water around the weir about 4' out from the weir.

Note: The seeping has increased compared to last week's inspection. We now have a continuous seep in the NE corner about 7' down, slow seep in the NW corner about 6' down, and seeping about 18' down which started two weeks ago as dripping.

Total rainfall amount up to the time of inspection was roughly 1.15".

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)